


Featuring
E123 Technology
Ball Mark Retrieval System


BEST AVAILABLE COPY

THE STEP BY STEP PROCESS


Acculinx



DIVOT MADE BY BALL FLIGHT




REPAIR DIVOT




SLIDE MARK OFF FOR
BALL PLACEMENT

AUTOMATIC BALL MARK RETRIEVAL PROCESS


E123 TECHNOLOGY



1ST, PLACE TURF REPAIR
FORK INSIDE POCKET



2ND, PICK UP MARK AND
PLACE INSIDE POCKET



3RD, RETRIEVE TURF REPAIR
FORK AND BALL MARK
AUTOMATICALLY LINKED
TOGETHER AT NEXT HOLE

BEST AVAILABLE COPY